

Release Notes

BTW 5.1.0.2800

January 03, 2007

Confidential and Proprietary Information

© Broadcom Corp., 2004, All rights reserved.
Printed in United States of America.
15435 Innovation Drive
San Diego, CA 92128
Phone: (858) 385-8800
Fax: (858) 385-8810

LICENSED SOFTWARE

© Copyright 2004, Broadcom® Corporation ("Broadcom"). All rights reserved.

WARNING:
This software and accompanying documentation are protected by copyright law and international treaties. Unauthorized reproduction or distribution of this software, or any portion of it, may result in severe civil and criminal penalties, and will be prosecuted to the maximum extent possible under the law.
Use of this software is governed by the terms of the end user license agreement that accompanies or is included with such software. Unless otherwise noted in the end user license agreement, or herein, no part of the documentation accompanying this software, whether provided in printed or electronic form may be reproduced in any form, or stored in a database or retrieval system, or transmitted in any form or by any means, or used to make any derivative work (such as translation, transformation, or adaptation) without the express, prior written consent of Broadcom.

Trademarks
Broadcom® and the pulse logo are trademarks of Broadcom Corporation and/or its subsidiaries in the United States and certain other countries. Microsoft® and Windows® are trademarks of Microsoft Corporation. Bluetooth® is a trademark of the Bluetooth SIG. Any other trademarks mentioned are the property of their respective owners.

BTW 5.1.0.2800

BLTH00066334 **Unknown**
BTW - Acer's application VCM does not work with BTW 5.1

Release Note:
Included support to connect to headset when service is set to Manual.

BLTH00074071 **Driver**
Win2K issue where after BTW install, the mouse is not functioning until reboot.

Release Note:
Switch device to UHE mode if reboot is required. Set a flag for btwdins service so that it does not switch device to HCI mode.

BLTH00076383 **unknown**
BT Tray Bar Icon

Release Note:
when command line " SetRegKeys" is passed, it should exit out btstack server. the code was missing there, added the code to exit out of btstack server for this command

---

BLTH00076418 **Localization**
Frames of accessibility tab on the Advanced Configuration are partially hidden on BR Windows XP.

Release Note:
Frames of accessibility tab on the Advanced Configuration are fine on BR Windows XP.

BLTH00076419 **Unknown**
The text box is cut off in the pairing window while using Polish language

Release Note:
The text box is not cut off in the pairing window while using Polish language

---

BLTH00076421 **Unknown**
The text box is cut off in the pairing window while using BR language

Release Note:
The text box is not cut off in the pairing window while using BR language

---

BLTH00076547 **DFU Wizard**
Have to run DFU wizard twice to complete the firmware upgrade on Dell laptop with XPP and VPP

Release Note:
change the compile setting.

BLTH00076673 **Driver**
frmupgr and btusbflt driver inf updates

BTW 5.1.0.2800

Release Note:
Updated driver files

BLTH00076799 **Unknown**
Logitech: Yellow bangs are created for BT COM ports after upgrading BTW 5.0.1.2703 to BTW

Release Note:
When USB device is not plugged in during upgrade, the installer needs to copy sys files to drivers folder.

BLTH00076819 **Stack Server**
PIM item transfer drops (or incorrectly parses) information when receiving calendar vcs items.

Release Note:
none

BLTH00077026 **Other**
Merge Cr <scm-bmt-autobuilder>

Release Note:
Merge Cr

BTW 5.1.0.2800

Pre-Installation Notices

1. User must be logged on as administrator to install BTW. If non-administrative user is logged on and starts install, and then inputs administrator password, BTW will not install correctly.
2. Remote installation of BTW is not allowed. Remote install does not provide sufficient privileges for the unsigned driver install.
3. If the system is configured to share contacts between Outlook Express and Microsoft Outlook, Outlook Express will not be shown as one of the options for PIM Item Transfer for business cards.
4. Install Shield Developer Premier 10.5 is required to build the BTW Release.
5. When doing a clean install on Windows 98SE, you will need to use the inst.exe to install, not setup.exe.
6. If end user stops the DFU process in the middle of the DFU upgrade, the BT device will stay in DFU upgrade mode. This will prevent the user from using the BT mouse/keyboard and the user will need to use wired mouse/keyboard in order to restart the DFU and complete upgrade process. You will then be able to use Bluetooth mouse/keyboard again.
7. Prior to installing BTW: Open Windows Explorer -> Tools -> Folder Options -> Check box "Launch folder windows in separate process". This will ensure that the task bar is always visible.
8. Following an upgrade installation, all local services and client application will require secure authentication.

Post-Installation Notices

1. If the client is set for NAP service, the Bluetooth Network adapter will not show that it is disconnected. Before using another Network access point, either reboot or manually renew the ip address.
2. Need to press OK in Control Panel/Sounds for MIDI files to play through headset. This is because Microsoft does not provide an API to set default MIDI device.
3. Volume level is set to maximum by default for Bluetooth Audio, once changed; it will retain its new setting.
4. Headset security uses the security of any headset shortcuts created.
5. In order to see traces in SpyLite, you will need to logoff of user account and log back in.
6. Some platforms cannot display the XP panel due to security setting for internet zones. For these platforms, the BT Neighborhood will switch to Classic View.

Create this registry entry:
DWORD HKCU\Software\WIDCOMM\BTConfig\Debug\LogIPAddr = 0x7f000001
Reboot.

BTW 5.1 Enhancements:

• Hands Free Profile to provide HFP functions for VOIP applications like Skype.
• Integrate Skype APIs to use headset button presses to Answer/Terminate/Reject calls

BTW 5.1 (LE) Version Limitations:

• The AV profiles (GAVDP, AVRCP, and A2DP) are disabled.
• The data rate is limited to Basic Rate only.

Installation Command Line Options

To install BTW from command line prompt or from a batch file, use the following command line options:

Setup.exe [/qn | /qb | /qr] [/nw] [/nodfu] [/L<LangId>] [/ru] [/ri]

/qn - Silent install without any UI and user interaction
/qb - Silent install with basic UI with progress dialog without any user interaction
/qr - Silent install with full UI without any user interaction

/nw- Setup.exe does not wait for BTW install to complete, exits after invoking MSI install.

/nodfu- Do not execute DFU during BTW install (even if configured for DFU in SvcPack.ini file)

/L -Installation language
<LangId> can be one of the following

1033: English
1046: Portuguese
1028: Chinese Tradition
2052: Chinese Simplified
1030: Danish
1043: Dutch
1035: Finnish
1036: French
1031: German
1040: Italian
1041: Japanese
1042: Korean
1044: Norwegian
1034: Spanish
1053: Swedish
1049: Russian
1045: Polish

/ru - Suppress reboot at the end of uninstall. (Relevant for Windows 98 and ME during upgrade)

/ri - Suppress reboot at the end of install (Relevant for Windows 98 and ME and if reboot is required on Windows 2000).

For example, to install silently without any UI in German language, use the following command line

setup.exe /qn /L1031