ESR1221Nx Changelog

Release Date April 14, 2011

Firmware version : 1.1.0.58
MD5 checksum : 95fdbb6e557d7826951f5fadc63485e8

WEB Version : 1.1.0

Fixed Bugs:

1.Fix wireless clients connect failure issue which user setting security encryption (WEP - ASCII) via Wizard.

2. Fix DUT will unstable issue when using BT to verified endurance test.

Release Date Feb. 24, 2011

Firmware version : 1.0.5.63
MD5 checksum :db338b0d23da6e0a334e9985786f0152

WEB Version : 1.0.5

Fixed Bugs:

1. Modify PIN code generating method.

Release Date Dec. 27, 2010

Firmware version : 1.0.4.59
MD5 checksum : e158d72a7a7a3ff1650bcaf6e89d126b

WEB Version : 1.0.4

Fixed Bugs:

1. Fixed WLAN display wrong channel issue.

Release Date Dec. 09, 2010

Firmware version : 1.0.3.56

MD5 checksum : a2e7525ec195530cb1b25a8cae90eaab

WEB Version : 1.0.3

Fixed Bugs:

1. Fixed reboot issue, that occurs when repeat connect/disconnect PPPoE in wan setting.

2. Fixed firmware upgrade fail cause system continue reboot issue.

3. Improve firmware recovery mode function. (boot loader)

Release Date Nov. 25, 2010

Firmware version : 1.0.1.52
MD5 checksum : 8910bc8bf079a2f1c850b76b387c2395

WEB Version : 1.0.1

Fixed Bugs:

1. Fix the web with special character display. (Issue 2.4.1 # 2, #3 , 2.6.1.2.1 #1))

2. Fix Monitor display . (Issue 2.4.1 #1)

Release Date Nov. 18, 2010

Firmware version : 1.0.0.48
MD5 checksum :2b4cf35d7b0801a83141aa739bcbddb7

WEB Version : 1.0.0

First Release

Default IP : 192.168.0.1